


Technical Standard – Electrical Outlet for Sump Pump



Lesson learned : When a GFCI outlet was tripped, the sump pump was not functioning. Homeowner was unaware that the GFCI was tripped. Single non-protected GFCI outlet recommended. Electrical shall confirm installation meets the electrical code of the municipality in which you are working and State of Wisconsin SPS-316 as apply.